



**Bean Elementary School**  
Proposed Improvements in 2018 Bond

<b><u>Improvement</u></b>	<b><u>Cost</u></b>
<b>Efficiency</b>	\$352,108
<i>Energy savings through partial replacement of old HVAC rooftop mechanical systems and replacement of the mechanical boiler equipment.</i>	
<b>Hardening Facilities for Safety and Security</b>	\$777,865
<i>Security measures include exterior lighting of building, directional signage, numbering of interior doors and exterior entries, and additional exterior door access control points.</i>	
<i>Also included is a secure vestibule that allows visitors to be screened and checked in before gaining entry into the hallway and replacement of PA system.</i>	
<i>Non-functioning doors and door hardware will also be replaced and additional cameras will be added to the existing surveillance system.</i>	
<b>Total</b>	<b>\$1,129,973</b>