



Stewart Elementary School
Proposed Improvements in 2018 Bond

<u>Improvement</u>	<u>Cost</u>
Efficiency	\$81,011
<i>Energy savings through partial replacement of old HVAC rooftop mechanical systems.</i>	
Hardening Facilities for Safety and Security	\$701,189
<i>Security measures include fencing, exterior lighting of building, directional signage, numbering of interior doors and exterior entries, and additional exterior door access control points.</i>	
<i>Also included is a secure vestibule that allows visitors to be screened and checked in before gaining entry into the hallway and replacement of PA system.</i>	
<i>Non-functioning doors and door hardware will also be replaced and additional cameras will be added to the existing surveillance system.</i>	
Total	\$782,200